**Bayer Built Woodworks** 



## **Warranty Information**

## QUALITY MILLWORK, UNBELIEVABLE SERVICE!

24614 US HWY 71 • BELGRADE, MN 56312	<b>PH</b> 320.254.3651	<b>FX</b> 320.254.3601	WWW.BAYERBUILT.COM
			1

## **Nature Series Wood**

(Limited 1 Year Warranty)

Bayer Built Woodworks provides a limited warranty to the original owner for one year from the date of the original invoice as long as proper installation, care, and maintenance guidelines are followed. This warranty covers defects in material and workmanship that may unreasonably affect a door's performance including, but not limited to, the following:

- Splits in door panels in excess of 1/16" inch in width
- Delaminating of stiles and rails in (lifting of veneer)
- Warping of doors in excess of ¼" inch
- Separation of stiles and rails in excess of 1/16" inch in width

In case of warping or stile/rail separation, door must be allowed to hang through a full heating and cooling season. Placement of your wood door is a major factor in performance; the proper overhang is required to provide necessary protection from the exterior elements.

## This Warranty Does Not Cover:

- Damage due to failure to follow proper installation, care, or maintenance instructions
- Damage due to failure to seal all six sides of the product within 90 days of invoice date
- Placing a door without providing proper overhang; minimum required overhang distance is half of your overhang height
- Any doors that have been cut-down in size or altered from original state
- Appearance of field finishing
- Decorative glass detail, glass is handcrafted so slight imperfections are acceptable
- Excess glazing on door glass
- Scratched glass
- Damage caused by attempting to repair the product
- Damage caused by others or by any cause beyond the control of Bayer Built Woodworks, including normal wear and tear, customer misuse, abuse, fire, flood, storm, or other acts of nature
- All components, parts, glass, and labor supplied by anyone other than Bayer Built Woodworks
- Exposure to acids, chemicals, or fumes
- Fading or discoloration due to UV or sunlight exposure
- Doors that are over 3'-6" in width and/or 8-0" in height
- Doors larger than 3'-0" x 7'-0" without a multi-point locking mechanism
- Natural variations in the color and/or texture of the wood
- Panel misalignment or shrinkage of 1/4" or less
- Expansion of bottom rail due to climate conditions
- Variation in stain absorption due to grain, color, or texture
- Damage caused by extreme temperature build-up where a storm door or dark paint or stain is utilized
- Use of non-vented storm doors; can cause excessive heat buildup causing finishing problems and warping issues

Bayer Built Woodworks maximum liability is the purchase price of the product; finish and installation costs are not covered by this warranty.

BAYER BUILT WOODWORKS SPECIFICALLY EXCLUDES ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE.

BUYERS SOLE AND EXCLUSIVE REMEDY FOR DAMAGES IS EITHER REPAIR OR REPLACEMENT OF THE PRODUCT AND SELLER SPECIFICALLY EXCLUDES ANY DAMAGES INCLUDING, BUT NOT LIMITED TO, CONSEQUENTIAL OR INCIDENTAL DAMAGES.

\*\*Warranties are non-transferable\*\*